

# SHARPY PLUS

EN PHOTOMETRIC DIAGRAMMS

ES DIAGRAMAS FOTOMÉTRICOS

IT DIAGRAMMI FOTOMETRICI


FR DIAGRAMMES PHOTOMETRIQUES

DE FOTOMETRISCHE DIAGRAMME

## Minimum Zoom, Beam mode (3°)

Total Output: 12000 lumens

lux (fc) 0      260000 (24154)    65000 (6039)    28889 (2684)    16250 (1510)




<b>Distance</b>	m (ft in)	0	10 (32' 10'')	20 (65' 7'')	30 (98' 5'')	40 (131' 3'')
<b>Diameter</b>	m (ft in)	0	0.52 (1' 9'')	1.05 (3' 5'')	1.57 (5' 2'')	2.09 (6' 10'')

## Minimum Zoom, Spot mode (3°)

Total Output: 12000 lumens

lux (fc) 0      60000 (5574)    15000 (1394)    6667 (619)    3750 (348)



<b>Distance</b>	m (ft in)	0	10 (32' 10'')	20 (65' 7'')	30 (98' 5'')	40 (131' 3'')
<b>Diameter</b>	m (ft in)	0	0.52 (1' 9'')	1.05 (3' 5'')	1.57 (5' 2'')	2.09 (6' 10'')


# SHARPY PLUS

- EN** PHOTOMETRIC DIAGRAM
- IT** DIAGRAMMI FOTOMETRICI
- DE** FOTOMETRISCHE DIAGRAMME

- ES** DIAGRAMAS FOTOMÉTRICOS
- FR** DIAGRAMMES PHOTOMETRIQUES


## Maximum Zoom, Beam mode (36°)

Total Output: 10500 lumens



## Maximum Zoom, Spot mode (36°)

Total Output: 10500 lumens



# SHARPY PLUS

- EN PHOTOMETRIC DIAGRAMS
- IT DIAGRAMMI FOTOMETRICI
- DE FOTOMETRISCHE DIAGRAMME

- ES DIAGRAMAS FOTOMÉTRICOS
- FR DIAGRAMMES PHOTOMETRIQUES

